

Comm Hill 2 Phase II Perimeter Sample Results

Week of November 11th through November 16th, 2019

Sampling Date	P1			P2			P3			P4			P5			P6		
	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc
11/11/2019	ND	1	0.0009	ND	ND	<0.0009	6	ND	0.0058	ND	1	0.0009	4	ND	0.0038	3	1	0.0038
11/12/2019	1	4	0.0047	4	2	0.0056	3	ND	0.0028	2	ND	0.0019	7	ND	0.0064	3	ND	0.0029
11/13/2019	2	4	0.0057	1	ND	0.0010	3	1	0.0041	4	1	0.0046	ND	ND	<0.0009	ND	ND	<0.0010
11/14/2019	ND	ND	<0.0009	2	1	0.0030	ND	ND	<0.0009	2	ND	0.0020	1	ND	0.0009	ND	ND	<0.0009
11/15/2019	ND	1	0.0010	ND	1	0.0010	1	ND	0.0010	3	ND	0.0030	ND	ND	<0.0010	2	ND	0.0020
11/16/2019	1	ND	0.0010	0.0010	0.0010	0.0010	ND	ND	<0.0010	ND	ND	<0.0009	ND	1	0.0010	ND	ND	<0.0010
BAAQMD Guidelines										<0.016 Structures/cc								

- 1 - Chrysotile Asbestos
- 2 - Amphibole Asbestos - Including regulated and non-regulated amphibole asbestos
- 3 - Structures/CC - Calculated Asbestos Structure Concentration per CC Air

ND Indicates that no asbestos structures were detected in the grid openings scanned

BAAQMD Guidelines Trigger Level for increased dust control measures