

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
1/5/26	NO EARTHWORK ACTIVITIES										
1/6/26	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090
1/7/26	< 0.0010	< 0.0010	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.0010	< 0.0010	< 0.0010	< 0.0010
1/8/26	NO EARTHWORK ACTIVITIES										
1/9/26	NO EARTHWORK ACTIVITIES										

\* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.