

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
1/12/26	< 0.0010	< 0.0010	0.0066	0.0009	< 0.00090	< 0.00090	< 0.00090	< 0.0010	< 0.00050	< 0.0010	0.0009
1/13/26	< 0.00090	< 0.00090	0.0009	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.0009	0.0028	0.0009	< 0.00090
1/14/26	< 0.00090	< 0.0010	0.0084	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.0046	0.0009	< 0.00090	0.0009
1/15/26	< 0.0010	pump fault	0.0087	0.0009	0.0019	< 0.0010	< 0.0010	< 0.0010	< 0.0010	0.0019	< 0.0010
1/16/26	< 0.0010	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.0018	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.