

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
2/9/26	< 0.00090	0.0009	< 0.00090	0.0009	< 0.0010	< 0.00090	< 0.0010	< 0.00090	0.0047	< 0.00090	< 0.00090
2/10/26	0.0028	< 0.00090	< 0.00090	< 0.00090	< 0.00090	pump fault	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090
2/11/26	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.015	< 0.00090	< 0.00090	< 0.00090	< 0.00090
2/12/26	< 0.0010	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.0009	< 0.00090	< 0.00090	< 0.00090	< 0.00090
2/13/26	< 0.0010	< 0.0010	< 0.0010	< 0.0010	0.0019	< 0.0010	< 0.0010	< 0.0010	< 0.0010	< 0.0010	< 0.00050

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.