

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
3/10/25	0.0049	0.001	< 0.0010	0.0079	0.004	0.003	0.004	0.013	0.0056	0.022	0.1
3/11/25	0.0028	0.0009	< 0.00090	< 0.00090	0.0028	0.0046	0.0065	0.0091	0.0055	0.019	0.025
3/12/25	No Grading Activities										
3/13/25	No Grading Activities										
3/14/25	No Grading Activities										

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.