

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
03/02/26	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.0094	< 0.00090	0.0019	0.0038	< 0.00090	< 0.00090	0.0009
03/03/26	< 0.00090	< 0.00090	0.0009	< 0.00090	0.019	< 0.00090	0.0009	< 0.00050	< 0.00090	0.0028	< 0.00090
03/04/26	< 0.00090	< 0.0010	< 0.00090	< 0.00090	0.055	0.0019	< 0.00090	pump fault	< 0.00090	< 0.0010	< 0.00090
03/05/26	< 0.00090	0.0009	< 0.00090	< 0.00090	0.022	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.0074	0.0019
03/06/26	< 0.0010	< 0.0010	0.0058	0.019	0.023	0.0096	0.1	0.001	< 0.00090	0.0037	0.001

\* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.