

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
3/16/26	0.0059	0.0072	0.01	pump fault	0.0058	0.001	0.0027	0.001	< 0.00090	0.0018	0.0036
3/17/26	< 0.00090	< 0.00090	< 0.0010	< 0.0010	0.0009	< 0.0010	pump fault	0.0027	0.0018	0.0018	< 0.0010
3/18/26	< 0.0010	< 0.00090	< 0.00090	< 0.00090	0.012	< 0.00090	0.0009	< 0.00090	< 0.00090	< 0.00090	< 0.00090
3/19/26	< 0.0010	< 0.0010	< 0.0010	< 0.0010	0.0038	< 0.0010	0.0019	< 0.0010	< 0.0010	0.017	0.0064
3/20/26	< 0.00090	< 0.00090	0.0028	0.0009	0.02	< 0.00090	< 0.00090	0.0028	0.0009	0.0038	< 0.00090

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.