

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
04/28/25	< 0.00090	< 0.00090	0.0045	< 0.00090	0.0045	< 0.00090	< 0.00090	< 0.00090	0.0049	0.0027	0.0081
04/29/25	0.0044	0.0027	0.0009	<0.00090	pump fault	<0.00090	0.033	0.0027	<0.00090	<0.00090	0.0018
4/30/25	<0.00090	0.0019	<0.00090	0.0056	0.0097	0.0009	0.0037	0.0028	<0.00090	0.0019	0.0037
5/1/25	0.001	0.0038	0.0019	0.0029	0.012	0.001	< 0.0010	0.0057	< 0.0010	< 0.0010	0.0085
5/2/25	0.0018	<0.00090	<0.00090	0.015	0.018	0.0009	<0.00090	0.0045	<0.00090	<0.00090	0.029

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.