

| | Station 1 NW Railroad: Exterior Perimeter | Station 2 SW Ridgline: Exterior Perimeter | Station 3 Corner of Donnici and Adeline Exterior Perimeter | Station 4 Altino and Donnici Corner: Exterior Perimeter | Station 5 Altino Blvd Park: Exterior Perimeter | Station 6 Fire Station Exterior Perimeter | Station 7 Empoli St: Exterior Perimeter | Station 8 Lina St Construction Entry: Exterior Perimeter | Station 9 Communications Hill Blvd Hill: Exterior Perimeter | Station 10 Railroad Center: Exterior Perimeter | Station 11 Quarry Entrance: Exterior Perimeter |
|--------|--|--|---|--|--|---|---|---|--|--|--|
| Date | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc | str/cc |
| 5/4/26 | 0.004 | < 0.0010 | 0.006 | 0.04 | 0.013 | 0.007 | < 0.0010 | 0.008 | 0.004 | 0.011 | 0.005 |
| 5/5/26 | < 0.0010 | 0.001 | < 0.0010 | 0.008 | < 0.0010 | < 0.0020 | < 0.0010 | 0.004 | < 0.0010 | 0.024 | < 0.0010 |
| 5/6/26 | < 0.0010 | < 0.0010 | 0.001 | 0.001 | 0.003 | < 0.0010 | < 0.0010 | 0.003 | < 0.0010 | 0.026 | 0.004 |
| 5/7/26 | < 0.0010 | < 0.0010 | 0.009 | 0.004 | 0.003 | 0.003 | 0.005 | 0.004 | 0.007 | 0.017 | 0.002 |
| 5/8/26 | < 0.0010 | < 0.0010 | < 0.0010 | 0.008 | 0.001 | pump fault | < 0.0010 | 0.004 | < 0.0010 | < 0.0010 | < 0.0010 |

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.