

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
5/26/25	NO EARTHWORK ACTIVITIES										
5/27/25	0.0036	0.011	0.0071	0.019	0.041	0.029	0.012	<0.00090	<0.00090	0.0072	0.0036
5/28/25	<0.00090	0.0037	0.019	0.018	0.023	0.021	0.019	pump fault	0.0028	0.024	0.019
5/29/25	<0.00090	0.0038	0.0019	0.0085	0.1	0.024	0.016	0.0056	<0.00090	0.0066	0.018
5/30/25	<0.00090	0.0019	0.012	0.0066	0.026	0.001	<0.0010	0.0018	0.0028	0.0083	0.013

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.