

|         | Station 1<br>NW Railroad:<br>Exterior<br>Perimeter | Station 2<br>SW Ridgline:<br>Exterior<br>Perimeter | Station 3<br>Corner of Donnici<br>and Adeline Exterior<br>Perimeter | Station 4<br>Altino and Donnici<br>Corner:<br>Exterior Perimeter | Station 5<br>Altino Blvd Park:<br>Exterior Perimeter | Station 6<br>Fire Station<br>Exterior Perimeter | Station 7<br>Empoli St: Exterior<br>Perimeter | Station 8<br>Lina St Construction<br>Entry: Exterior<br>Perimeter | Station 9<br>Communications Hill<br>Blvd Hill:<br>Exterior Perimeter | Station 10<br>Railroad Center:<br>Exterior Perimeter | Station 11<br>Quarry Entrance:<br>Exterior Perimeter |
|---------|--|--|---|--|--|---|---|---|--|--|--|
| Date    | str/cc   | str/cc   | str/cc  | str/cc   | str/cc   | str/cc  | str/cc  | str/cc  | str/cc   | str/cc   | str/cc   |
| 6/22/26 | 0.01   | 0.002  | 0.001   | < 0.0010   | 0.001  | < 0.0010  | < 0.0010                                      | 0.002   | 0.003  | 0.013  | 0.002  |
| 6/23/26 | < 0.0010   | < 0.0010   | 0.001   | < 0.0010   | 0.002  | < 0.0010  | 0.001   | 0.002   | 0.001  | 0.003  | 0.001  |
| 6/24/26 | 0.004  | 0.001  | pump fault  | 0.02   | 0.004  | 0.002   | 0.002   | 0.005   | 0.001  | 0.011  | 0.016  |
| 6/25/26 | 0.001  | < 0.0010   | 0.002   | 0.007  | 0.01   | 0.001   | 0.004   | 0.028   | < 0.0010   | 0.005  | 0.004  |
| 6/26/26 | < 0.0010   | < 0.0010   | 0.004   | 0.009  | 0.002  | 0.001   | 0.001   | 0.009   | 0.002  | < 0.0010   | < 0.0010   |

\* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.