

Comm Hill 2 Phase II Perimeter Sample Results

Week of September 16th through September 21th, 2019

Sampling Date	P1			P2			P3			P4			P5			P6		
	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc
9/16/2019	1	ND	0.0010	ND	ND	<0.0010	3	1	0.0039	4	ND	0.0039	ND	ND	<0.0010	ND	ND	<0.0010
9/17/2019	ND	ND	<0.0009	1	ND	0.0009	11	ND	0.0105	3	ND	0.0028	3	ND	0.0030	1	ND	0.0009
9/18/2019	ND	ND	<0.0010	ND	ND	<0.0010	3	ND	0.0028	ND	ND	<0.0010	ND	ND	<0.0010	ND	ND	<0.0010
9/19/2019	1	ND	0.0009	ND	ND	<0.0010	2	2	0.0036	16	ND	0.0160	ND	ND	<0.0010	ND	ND	<0.0009
9/20/2019	1	ND	0.0010	ND	1	0.0010	3	1	0.0039	ND	ND	<0.0009	ND	ND	<0.0009	ND	ND	<0.0009
9/21/2019	1	ND	0.0009	1	ND	0.0010	3	ND	0.0029	5	ND	0.0048	3	ND	0.0028	ND	ND	<0.0009
BAAQMD Guidelines											<0.016 Structures/cc							

- 1 - Chrysotile Asbestos
- 2 - Amphibole Asbestos - Including regulated and non-regulated amphibole asbestos
- 3 - Structures/CC - Calculated Asbestos Structure Concentration per CC Air

ND

Indicates that no asbestos structures were detected in the grid openings scanned

BAAQMD Guidelines Trigger Level for increased dust control measures