

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
10/06/25	< 0.00090	0.0009	0.0018	< 0.00090	<0.00090	0.0018	< 0.00090	0.0019	0.0009	0.0009	0.012
10/07/25	0.0009	< 0.00090	< 0.0010	0.001	<0.0010	< 0.0010	0.0039	< 0.0010	0.001	< 0.0010	0.0047
10/08/25	< 0.00090	0.0019	< 0.00090	0.0009	0.0019	0.0009	0.0018	0.0019	0.0037	0.0009	0.0037
10/09/25	0.0009	< 0.00090	0.0009	0.0009	<0.00090	0.0018	0.0036	0.0037	< 0.00090	0.0037	0.0083
10/10/25	0.0019	0.0009	0.0009	0.0038	0.027	< 0.00090	< 0.0010	< 0.00090	0.0009	0.0083	0.0037

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.