

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
11/3/25	pump fault	0.011	< 0.00090	0.0027	0.0027	< 0.0010	0.001	< 0.00090	< 0.00090	0.0027	0.0046
11/4/25	0.0046	< 0.00090	0.0009	0.011	0.0019	< 0.00090	< 0.00090	0.0045	< 0.00090	0.0009	< 0.00090
11/5/25	NO EARTHWORK ACTIVITIES										
11/6/25	NO EARTHWORK ACTIVITIES										
11/7/25	N/A	< 0.00090	0.026	0.0009	0.028	< 0.00090	0.003	< 0.00090	< 0.00090	0.0063	0.0009

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.