

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
11/24/25	< 0.0010	< 0.0010	0.0019	< 0.0010	0.0049	0.0049	< 0.00090	< 0.00090	< 0.00090	< 0.0010	0.001
11/25/25	0.0054	pump fault	pump fault	< 0.00090	0.0044	< 0.00090	< 0.00090	0.01	< 0.00090	0.0009	0.018
11/26/25	< 0.00090	< 0.00090	< 0.0010	< 0.0010	< 0.00090	0.0018	< 0.0010	< 0.0010	< 0.00090	< 0.00090	< 0.0010
11/27/25	NO EARTHWORK ACTIVITIES										
11/28/25	NO EARTHWORK ACTIVITIES										

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.