

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
12/1/25	< 0.0010	< 0.0010	< 0.00090	< 0.0010	0.0018	0.003	0.0037	0.0018	0.001	0.001	pump fault
12/2/25	< 0.00090	0.0018	0.0084	0.0028	0.0009	0.0018	0.0027	< 0.00090	0.0045	0.0009	< 0.00090
12/3/25	0.0009	< 0.00090	0.013	0.0028	0.0038	< 0.00090	< 0.0010	0.013	0.0027	0.0027	pump fault
12/4/25	0.0062	0.0009	< 0.00090	< 0.00090	0.0018	< 0.00090	< 0.00090	0.0009	< 0.0010	< 0.00090	< 0.00090
12/5/25	0.001	0.001	0.0018	0.0009	0.0027	0.0009	0.0009	< 0.00090	< 0.00090	0.0018	< 0.00090

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.