

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 Corner of Donnici and Adeline Exterior Perimeter	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construction Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
12/8/25	< 0.00090	< 0.00090	< 0.00090	< 0.00090	0.02	0.0028	< 0.00090	0.0009	< 0.00090	< 0.00090	pump fault
12/9/25	< 0.0010	0.0019	< 0.00090	0.03	0.012	0.0009	0.0029	0.0048	< 0.00050	0.001	0.001
12/10/25	0.2	< 0.00090	0.0028	0.019	0.084	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090
12/11/25	0.0074	< 0.0010	< 0.0010	0.4	0.031	< 0.00090	0.0028	< 0.00090	< 0.0010	0.0044	< 0.0010
12/12/25	< 0.0010	< 0.00090	< 0.0010	< 0.0010	< 0.0010	< 0.0010	< 0.00090	< 0.00090	< 0.00090	< 0.00090	< 0.00090

* Sample time limited by pump fault. Analysis and calculations made from total time indicated on sample pump.