

	Station 1 NW Railroad: Exterior Perimeter	Station 2 SW Ridgline: Exterior Perimeter	Station 3 N/A	Station 4 Altino and Donnici Corner: Exterior Perimeter	Station 5 Altino Blvd Park: Exterior Perimeter	Station 6 Fire Station Exterior Perimeter	Station 7 Empoli St: Exterior Perimeter	Station 8 Lina St Construcion Entry: Exterior Perimeter	Station 9 Communications Hill Blvd Hill: Exterior Perimeter	Station 10 Railroad Center: Exterior Perimeter	Station 11 Hillcap Ave. Hill Side: Exterior Perimeter	Station 12 Hillsdale Ave SE Location: Exterior Perimeter	Station 13 Hillsdale Ave. N Quarry Entrance: Exterior Perimeter
Date	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc	str/cc
12/9/24	0.0009	< 0.00090	< 0.00090	< 0.0010	< 0.0010	< 0.0010	< 0.0010	< 0.0010	< 0.0010	0.0095	< 0.00090		
12/10/24	0.0009	< 0.00090	pump fault	< 0.00090	< 0.00090	< 0.00090	0.0028	0.0068	0.01	0.0018	0.0019		
12/11/24	< 0.00090	< 0.00090	0.0019	0.001*	0.0029*	< 0.0010	< 0.00090	0.0018	0.0018	0.001	0.0065	Out of scope - No grading operations	Out of scope - No grading operations
12/12/24	NO EARTHWORK ACTIVITIES												
12/13/24	NO EARTHWORK ACTIVITIES												

\* Sample time limited by pump fault. Analysis and calculations made from total time indiated on sample pump.