

Comm Hill 2 Phase II Perimeter Sample Results

Week of May 22th through May 26th, 2023

Sampling Date	P1			P2			P3			P4			P5		
	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³
5/22/2023				ND	ND	<0.0010							ND	ND	<0.0010
5/23/2023				ND	ND	<0.0010							ND	ND	<0.0010
5/24/2023				ND	ND	<0.0010							ND	ND	<0.0010
5/25/2023				ND	ND	<0.0010							ND	ND	<0.0010
5/26/2023															
BAAQMD Guidelines										<0.016 Structures/cc					

Sampling Date	P6			P7			P8			P9d			P10e		
	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³	Chrysotile	Amphibole ²	Structures/cc ³	Chrysotile ¹	Amphibole ²	Structures/cc ³
5/22/2023	ND	ND	<0.0010	ND	ND	<0.0010	ND	ND	<0.0010	ND	ND	<0.0010	ND	ND	<0.0010
5/23/2023	3	ND	0.0031	ND	ND	<0.0010	ND	ND	<0.0010	2	ND	0.0021	2	ND	0.0020
5/24/2023	ND	ND	<0.0010	5	1	0.0059	ND	ND	<0.0010	3	ND	0.0030	ND	ND	<0.0010
5/25/2023	ND	ND	<0.0010	1	ND	0.0010	ND	ND	<0.0010	ND	ND	<0.0010	3	ND	0.0030
5/26/2023															
BAAQMD Guidelines										<0.016 Structures/cc					

1 - Chrysotile Asbestos

2 - Amphibole Asbestos - Including regulated and non-regulated amphibole asbestos

3 - Structures/CC - Calculated Asbestos Structure Concentration per CC Air

ND Not Detect

BAAQMD Guidelines Trigger Level for increased dust control measures

NM Not Measured

1/20/2022 Sampling Location moved from P10d to P10e