

Comm Hill 2 Phase II Perimeter Sample Results

Week of September 23rd through September 28th, 2019

Sampling Date	P1			P2			P3			P4			P5			P6		
	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc
9/23/2019	1	ND	0.0009	4	ND	0.0039	2	1	0.0029	21	ND	0.0236	6	1	0.0067	10	ND	0.0099
9/24/2019	4	1	0.0049	6	ND	0.0057	3	1	0.0036	18	2	0.0184	2	1	0.0029	1	1	0.0019
9/25/2019	ND	ND	<0.0009	5	ND	0.0047	6	ND	0.0056	20	ND	0.0193	21	ND	0.0202	10	3	0.0123
9/26/2019	1	1	0.0020	5	2	0.0065	5	1	0.0057	12	4	0.0152	6	ND	0.0056	6	1	0.0069
9/27/2019	1	ND	0.0009	2	ND	0.0020	4	1	0.0048	1	ND	0.0010	1	ND	0.0010	ND	ND	<0.0010
9/28/2019	1	ND	0.0010	ND	ND	<0.0009	2	ND	0.0020	ND	ND	<0.0010	ND	ND	<0.0010	ND	ND	<0.0010
BAAQMD Guidelines											<0.016 Structures/cc							

- 1 - Chrysotile Asbestos
- 2 - Amphibole Asbestos - Including regulated and non-regulated amphibole asbestos
- 3 - Structures/CC - Calculated Asbestos Structure Concentration per CC Air

ND Indicates that no asbestos structures were detected in the grid openings scanned

BAAQMD Guidelines Trigger Level for increased dust control measures