

Comm Hill 2 Phase II Perimeter Sample Results

Week of September 9th through September 14th, 2019

Sampling Date	P1			P2			P3			P4			P5			P6		
	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc	Chrysotile	Amphibole	Structures/cc
9/9/2019	NA	NA	NA	ND	ND	<0.0009	10	1	0.0101	5	ND	0.0047	NA	NA	NA	1	ND	0.0009
9/10/2019	ND	1	0.0010	ND	ND	<0.0010	3	1	0.0039	3	ND	0.0030	2	ND	0.0020	ND	ND	<0.0009
9/11/2019	1	ND	0.0010	3	ND	0.0030	5	1	0.0058	6	ND	0.0055	ND	ND	<0.0010	1	ND	0.0010
9/12/2019	8	ND	0.0075	1	ND	0.0009	2	2	0.0037	2	1	0.0028	14	ND	0.0138	2	ND	0.0020
9/13/2019	7	ND	0.0068	3	2	0.0049	12	4	0.0159	14	ND	0.0139	4	ND	0.0037	10	ND	0.0098
9/14/2019	ND	1	0.0010	ND	ND	<0.0010	ND	2	0.0019	4	ND	0.0040	1	1	0.0020	3	ND	0.0030
BAAQMD Guidelines											<0.016 Structures/cc							

- 1 - Chrysotile Asbestos
- 2 - Amphibole Asbestos - Including regulated and non-regulated amphibole asbestos
- 3 - Structures/CC - Calculated Asbestos Structure Concentration per CC Air

ND Indicates that no asbestos structures were detected in the grid openings scanned

BAAQMD Guidelines Trigger Level for increased dust control measures